



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report

#### Minerals Regulatory Program

April 27, 2007

Supervisor RQZ

**Mine Name:** Timberline Rock Pit  
**Operator Name:** Timberline Rock Pit, LLC  
(Matt Carter)  
**Inspector(s):** Lynn Kunzler, DOGM  
**Other Participants:** None  
**Mine Status:** No activity

**Permit number:** S/049/053  
**Inspection Date:** April 4, 2007  
**Time:** 8:30 am

#### Elements of Inspection

1. Permits, Revisions, Transfer, Bonds
2. Public Safety (shafts, adits, trash, signs, highwalls)
3. Protection of Drainages / Erosion Control
4. Deleterious Material
5. Roads (maintenance, surfacing, dust control, safety)
6. Concurrent Reclamation
7. Backfilling/Grading (trenches, pits, roads, highwalls,
8. Soils
9. Revegetation
10. Other

Evaluated	Comment	Enforcement
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

#### Purpose of Inspection:

This was a routine inspection while in the area.

#### Inspection Summary:

The site has not been active since last year. Most of the the 5- acre site is currently disturbed (several pits, overburden piles, etc.) During the inspection in May of 2006, a cessation order had been issued for operating outside the 5-acre limit for a small mining operation. The CO was terminated November 6, 2006 after being modified to allow reclamation of the area outside the proposed permit area. (The party responsible for operating outside the area had reclaimed and seeded the area subject of the CO prior to November 1 and has provided surety to assure successful revegetation.

Photos were taken to document site conditions.

#### Conclusions and Recommendations:

Continue to monitor reclamation success when in the area.

**Inspector's Signature** LK

LK:pb

O:\M049-Utah\S0490053-Timberline\inspections\Insp-04042007.doc